


Auto White for Color imaging in Elements



1. Go to a white area on slide (no tissue!)
2. Under the Color DS-Ri2 Setting tab:
 - a) Click the “AE button
 - b) Click Auto White
 - Check the “LUTS” window – the red green and blue histograms (little hills) should line up
3. Click the triangle next to “BF” in the OC panel to make the computer remember

Note: Only need to do this once at the beginning of imaging session!

A. 



LUTS Window



Click arrow next to BF to apply auto white settings